

Photo Sheet

Tri-State Adjusting Service

Po Box 253
Mead, WA 99021
office: (509)891-7703
fax: (509)891-7734
cell: (509)844-5582

Insured: CLMT Jackie Peebles

Claim #: KT2017062620

Policy #:



1-Left Quarter

Date Taken:

Taken By: Dave

Repair left quarter



2-Rear Deck Lid

Date Taken:

Taken By: Dave

deck lid under repair

Photo Sheet

Tri-State Adjusting Service

Po Box 253
Mead, WA 99021
office: (509)891-7703
fax: (509)891-7734
cell: (509)844-5582

Insured: CLMT Jackie Peebles

Claim #: KT2017062620

Policy #:



3-Left Quarter

Date Taken:

Taken By: Dave

Left quarter panel repair



4-Left rear

Date Taken:

Taken By: Dave

Shows repair and deck lid

Photo Sheet

Tri-State Adjusting Service

Po Box 253
Mead, WA 99021
office: (509)891-7703
fax: (509)891-7734
cell: (509)844-5582

Insured: CLMT Jackie Peebles

Claim #: KT2017062620

Policy #:



5-Left side Jamb

Date Taken:

Taken By: Dave

Let side jamb



6-Full view

Date Taken:

Taken By: Dave

Left side under repair

Photo Sheet

Tri-State Adjusting Service

Po Box 253
Mead, WA 99021
office: (509)891-7703
fax: (509)891-7734
cell: (509)844-5582

Insured: CLMT Jackie Peebles

Claim #: KT2017062620

Policy #:



7-Left inner

Date Taken:

Taken By: Dave

Left inner w/ trim removed



8-Left rocker

Date Taken:

Taken By: Dave

Left rocker removed

Photo Sheet

Tri-State Adjusting Service

Po Box 253
Mead, WA 99021
office: (509)891-7703
fax: (509)891-7734
cell: (509)844-5582

Insured: CLMT Jackie Peebles

Claim #: KT2017062620

Policy #:



9-Left roof MLD

Date Taken:

Taken By: Dave

Left roof MLD removed



10-Left window

Date Taken:

Taken By: Dave

Rear quarter panel window removed

Photo Sheet

Tri-State Adjusting Service

Po Box 253
Mead, WA 99021
office: (509)891-7703
fax: (509)891-7734
cell: (509)844-5582

Insured: CLMT Jackie Peebles

Claim #: KT2017062620

Policy #:



11-Inside

Date Taken:

Taken By: Dave

Inside



12-Left side

Date Taken:

Taken By: Dave

Prior to repair

Photo Sheet

Tri-State Adjusting Service

Po Box 253
Mead, WA 99021
office: (509)891-7703
fax: (509)891-7734
cell: (509)844-5582

Insured: CLMT Jackie Peebles

Claim #: KT2017062620

Policy #:



13-Right side

Date Taken:

Taken By: Dave

Before repair



14-Vin Tag

Date Taken:

Taken By: Dave

Shows Vin tag